

A photograph of a worker in a trench next to a manhole cover. The worker is wearing a grey glove and is using a tool to work on the cover. A yellow lifting block is placed on the cover, and a metal frame is visible above it. The cover has a grid pattern and some text on it. A semi-transparent circular overlay is on the right side of the image, containing the title and subtitle.

Status på fjernvarmedriften - nye aktiviteter

Avedøre Fjernvarme v/EBO Consult A/S

7. april 2022

Nye driftsaktiviteter – 1. halvår 2022

December

- Kedel kørsel
- Lækage på gymnasiet
- Rengøring

Januar

- Vekslerblade skiftes
- Centralen males

Februar

- Besøg af datacentral

Marts



- Renovering af låse i hoveddør

April

Maj

Centralen

- Renovering af veksler



PLADER I AVEDØRE HAR EN VINKEL PÅ 35 GRADER ANDRE
PLADER HAVDE EN VINKEL PÅ VINKEL
60 GRADER

